### CERTIFICATE OF ANALYSIS

Milbank Manufacturing Company

1400 E. Havens P.O. Box 754

Kokomo, IN 46903-0754 Attn: Ronda S. Yeakley

Purchase Order: 206941

Invoice Number:

Order #: 98-03-606 Date: 03/20/98 09:22

Work ID: Effluent Water Composite

Date Received: 03/18/98 Date Completed: 03/19/98

Client Code: MILBANK MFG

### SAMPLE IDENTIFICATION

i i mari i din kananan nya mpi gita ayan iya

Sample

Sample

Number Description

01 Effluent, Water Composite

Sample

Sample

Number

Description

This report may not be reproduced except in full, without the

written approval of the laboratory. All results relate only

to the items tested.

This report contains a total number of pages: 02

Certified By





Order # 98-03-606 03/20/98 09:22


TEST RESULTS BY SAMPLE

Page 2

Sample: 01AW Effluent Water Composite Collected: 03/17/98 Category: WATER

Test Description	Result	Limit	Units	Analyzed	Ву
Iron, ICAPES	1.550	0.010	mg/L	03/19/98	JAR
Lead, ICAPES	<0.040	0.040	mg/L	03/19/98	JAR
Silver, ICAPES	<0.010	0.010	mg/L	03/19/98	JAR
Zinc, ICAPES	3.470	0.010	mg/L	03/19/98	JAR







# ESC boratories

5933 West 71st Street \* Indianapolis, IN 46278 Phone (317) 290-1471 \* Fax (317) 290-1670

## CHAIN OF CUSTODY RECORD

Project No: Project Name:			ESG Work Order #:		Total	Filtered (Y or N) Preserv. Code  Analyses  A = Acid B = Base C = Cool 4  Comments										l l		
Sampler(s) Signature:				Number of				/ /		//	/ ,	//	//		B = Base C = Cool 4°			
Stat.No	DATE	TIME	СОМР	GRAB	STATION LO		Containers	$ \angle $	Mr.	$\angle$			$\angle$	$\angle$	$\angle$	$\angle$	Comments	
	2-17-95	مدو الاح	×		Eff.	P,T	1	1							-			
							_	<del> </del>	-						-		1	
								-										
	<del>,</del>																	
					***************************************													
																,		
Relingui	ished By:		Date /	Time	Received By:		Date / Time	Addi	ional	Inform	nation:	<u></u>						
6,79 als 3-19-98 Juesa Byros				3/91,00 1/8	Turn Around Time: Normal Rush Report Due:													
Relinquished By: Date / Time Received By: Date / Time Are samples suspected to be: Flammable Corrosive							Toxic \											
				m.			D 4 4 M		Were	sampl	es rec	eived	intact	and p	proper	ly pre	served? Yes	No Service
Relinqui	ished By:		Date /	Time	Received By:		Date / Time	Temp. Blank°C										